

TERMINAL BACKGROUND

Jefferson Railport Terminal is located on a 250 acre site on the east bank of the Neches River at the Port of Beaumont. The site sits strategically at the confluence of three Class 1 rail carriers and multiple major refineries.

The site commenced operation in late 2013, and has a gross capacity of approximately 1,000,000 barrels of storage capacity for various refinery crude oil feed stocks. The Terminal also has marine capabilities including a ship dock and a dedicated inland barge dock.

Future plans include additional storage capacities of up to 3.5 MM barrels, pipeline connections and ship docks.



SITE SAFETY RULES

*Safety is the Priority.
Every job. Every day.*

ENERGY IN MOTION



CONTACT US

JEFFERSON ENERGY BEAUMONT OFFICE
Edison Plaza Building
350 Pine Street Suite 1000
Beaumont, Texas 77701

(409) 239.5383 | mviator@jeffcorefinery.com

www.JeffersonEnergyCo.com

WELCOME TO OUR TERMINAL

We hope and expect your visit to be productive, but more importantly, safe. As such, we do expect visitors to help us provide a safe work environment by adhering to the basic safety principles of the site.

BASIC SAFETY

- Speed limit while driving 15 mph
- Smoking in designated areas only.
- No drugs or alcohol permitted on site.
- Drinking and/or eating in designated areas.
- No cell phone cameras allowed in operational areas.
- No lighters, matches, or other spark-producing devices permitted.
- Report any injury or spill to Jefferson immediately
- No firearms permitted on site.



SAFETY ABSOLUTES

1. Being on an elevated work surface above 6 feet where fall protection is required.
2. Being on a dock within six feet of the water's edge without flotation device or inside fixed handrails.
3. Working on equipment to perform work without ensuring that the power and other energy source have been rendered inoperative.
4. Entering a confined space that has not been isolated, the atmosphere checked and permitted as a safe place to enter.
5. Walking, standing or working under an elevated load.

PERSONNEL PROTECTIVE EQUIPMENT

While on site in operational areas, the following PPE is required:

1. Safety glasses with side shields
2. Steel Toed Shoes
3. Flame Resistant shirt and pants
4. Hard Hat

EVACUATION PROCEDURE

We do not expect that an evacuation will occur while visiting our terminal. If one occurs:

1. Do not panic.
2. Shut down equipment.
3. Walk to the nearest evacuation muster location.